

PALIToy REGD

ACTION man

BELT FEED MACHINE GUN ASSEMBLY AND FIRING INSTRUCTIONS

1. PUSH REAR LEG OF TRIPOD INTO SLOT.
2. PUSH FRONT LEGS OF TRIPOD IN SLOT ON OPPOSITE SIDE.
3. PUSH ASSEMBLED TRIPOD UP INTO HOLE UNDERNEATH MACHINE GUN.
4. PLACE BATTERIES INTO AMMUNITION BOX AS ILLUSTRATED AND PUT ON LID.
5. PULL TRIGGER TO FIRE.
6. IF THE BARREL SHOULD REMAIN LIT, AFTER FIRING, PULL BELT UNTIL LIGHT GOES OUT.
7. USE 2 HP7 BATTERIES

