


STEP 6—ACTION-MAN IS READY FOR DEEP SEA DIVING

BLOW AIR DOWN TO ACTION-MAN DEEP SEA DIVER



Lower Action-Man into water by holding onto air hose. Lower slowly until his weighted diving boots rest squarely on the bottom . . . Action Man's marker buoy will bob to the surface. Now blow air down to your deep sea diver using your mouth pump. Action Man will send air bubbles to the surface just like a real deep sea diver. When you blow more air to your diver he will rise to the surface.

TIE LIFE LINE TO BELT

Action-Man is ready for action anywhere — your bathtub, wading pool, swimming pool, pond, lake or sea shore.

NOTE: After using Action-Man in the water, remove all equipment and set it out to dry. The suit may be hung out or put into an automatic dryer. **DO NOT LEAVE SUIT IN DRYER FOR ANY EXTENDED PERIOD OF TIME.**

INSTRUCTIONS TO PREPARE ACTION-MAN'S DEEP SEA DIVING EQUIPMENT

THIS EQUIPMENT HAS BEEN DESIGNED FOR USE WITH ACTION MAN —THE MOVABLE FIGHTING MAN.

IMPORTANT:

Your Action-Man Deep Sea Diving Equipment will last a long time if you take care of it. Official Navy divers always take care of their equipment.

STEP 1—TO REMOVE HELMET

AIR HOSE ATTACHED TO BACK OF HELMET

FACE PLATE



Grasp breast plate firmly with one hand and push downward. At the same time being careful not to touch face plate, unscrew helmet anti clock-wise and lift off.

NOTE: Be sure air hose does not tangle.

STEP 2—TO REMOVE WEIGHTED DIVING BELT


Unsnap weighted belt at back and slide straps off shoulders.

WEIGHTED BELT

STEP 3—TO REMOVE BREAST PLATES

Lift off outside breast plate. Remove inside breast plate by pulling up through elastic neck opening of diving suit.

GLOVES



STEP 4—REMOVE WEIGHTED BOOTS, PLASTIC BOOTS AND GLOVES


Take plastic form from inside diving suit.

WEIGHTED BOOTS

STEP 5 — NOW YOU ARE READY TO DRESS ACTION-MAN SAILOR FOR DEEP SEA DIVING

Remove all of Action Man's clothing. Take your undressed Action Man and put on his waterproof suit.

DRAWING A




Place Action-Man in his suit feet first through the neck opening. Feet should be pointed downward. See drawing (A). Slide arms into sleeves.

DRAWING B




Now put inside breast plate (plate with screw thread) over Action-Man's head. Recess in thread should face forward under Action-Man's chin. See drawing (B). Breast plate fits inside suit. Spread the elastic neck area so that the plate can fit inside suit on Action-Man's shoulders. Put boots and boot weights on.

DRAWING C




Place outside breast plate, drawing (C), over Action-Man's head with oval panel facing front. Be sure outside breast plate is pushed down as far as possible and rests evenly over Action Man's suit.

DRAWING D



1. Grasp breast plate firmly with one hand and push downward.
2. The helmet is placed over Action-Man's head and turned clock-wise onto the thread of the inside breast plate. See drawing (D). The face plate should face forward when helmet is completely on tight. **DO NOT HOLD THE FACE PLATE WHEN HANDLING HELMET.**

DRAWING E



The weighted diving belt is put on by placing Action-Man's arms through the shoulder straps, as shown in drawing (E), and slipping belt around his waist. Slide shoulder straps over outside breast plate. Snap belt closed. Bring lower centre strap from front between Action-Man's legs and snap to belt in back. Put gloves on. Make sure that gloves are pulled tight over wrists.